

MAL 8553

236/2016* MALAYSIA – Sabah – Sandakan – Pulau Berhala – Light Beacon.

Source: National Hydrographic Centre.

Chart MAL 8553 (Last Correction NE/2016) WGS 84 DATUM

Substitute  FI(2)6s7m5M for
 FI(2)6s7m5M 05° 51'.66N, 118° 08'.45E

53/2017 MALAYSIA – Sabah – Pulau Berhala – Beacon.

Source: Sabah Marine Department.

Chart MAL 8553 (Last Correction 236/2016) WGS 84 DATUM

Delete  FI.6.10s194m28M 05°52'.14N, 118°09'.06E

158*/2017 MALAYSIA – Sabah – Pulau Tiong Kechil – Light beacons.

Source: Sandakan Hydrographic Office.

Chart MAL 8553 (Last Correction 53/2017) WGS 84 DATUM

Insert  FI.R.2s 05°46'.87N, 118°01'.55E
 FI.R.2s 05°46'.91N, 118°01'.38E

160(T)*/2017 MALAYSIA – Sabah – Pulau Tiong Kechil – Buoy.

Source: Sandakan Hydrographic Office.

1. The red conical buoy, in position 05°47'.00N., 118°02'.00E. is reported missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 8553 – MAL 8617.
-

35*/2018

MALAYSIA – Sabah – Tg. Aru – Anchorage area.

Source: National Hydrographic Centre.

Chart MAL 8553 (Last Correction 160/2017) WGS 84 DATUM

Insert

limit of anchorage area, pecked line, joining: (a) 05° 50'.00N, 118° 08'.27E
(b) 05° 50'.00N, 118° 09'.33E