

MAL 6436

103/2012* **Malaysia – Terengganu – Kertih Port – Light beacon.**

Source: Marine Department Peninsular Malaysia No. 30/2012.

Chart MAL 6436 (Last Correction 198/2008) WGS 84 DATUM

Insert



Kertih Front Light Beacon
Fl.2s12M

04° 34'.77N, 103° 27'.73E



Kertih Rear Light Beacon
Fl.2s12M

04° 34'.57N, 103° 27'.38E

53/2016 **MALAYSIA – Terengganu – Pelabuhan Kertih – Range and Light Beacon.**

Source: Kertih Port Sdn Bhd.

Chart MAL 6436 (Last Correction 103/2012) WGS 84 DATUM

Amend

range to, 2.5 – 4.4M for 25 – 19M &
0.7 – 1.3M for 14 – 10M

04°35'.45N, 103°27'.38E

Delete



Kertih Front Light
Beacon Fl.2s12M

(a) 04° 34'.77N, 103° 27'.73E



Kertih Rear Light
Beacon Fl.2s12M

(b) 04° 34'.57N, 103° 27'.38E

108(T)*/2020 **MALAYSIA – Terengganu – Pelabuhan Kertih – Buoy.**

Source: Marine Department of Malaysia No. 107(T), 109(T)/2020.

1. Kertih N2 buoy, *Fl.Y.4s*, in position 04°34'.10N, 103°28'.52E and Kertih Port No 7 buoy, *Fl(4)5s5M*, in position 04°35'.30N, 103°27'.50E is temporarily unlit.
2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
3. Charts affected –MAL 6436.

127*/2020 **MALAYSIA – Terengganu – Pelabuhan Kertih – Buoys.**

Source: Marine Department of Malaysia No. 137, 138/2020.

1. Kertih Port No 7 buoy, *Fl(4)5s5M*, in position 04°35'.30N, 103°27'.50E and Kertih N2 buoy, *Fl.Y.4s*, in position 04°34'.10N, 103°28'.52E is restored to normal.
 2. Former Notice No. 108/2020(T) is cancelled.
 3. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 4. Charts affected – MAL 6436.
-