

126*/2023 MALAYSIA – Selat Manjung (Dinding) – Light Beacon.

Source: Marine Department of Malaysia No. 153/2023.

1. Dinding Light Beacon, FI(2)G.5s6M, in position 04°14'.68N, 100°34'.88E is restored to normal.
 2. Former Notice No. 186(T)*/10 is cancelled.
(WGS84)
 3. Chart affected – MAL 5425.
-