

Source: Marine Department of Malaysia No. 56/2022.

1. Tanjung Layar Light Beacon Fl(2)5s, in position 02°51'.29N, 104°08'.98E is restored to normal.
 2. Former Notice No. 42(T)*/22 is cancelled.
(WGS84)
 3. Charts affected – MAL 6257
-