

**Source: Marine Department of Malaysia No. 56/2022.**

1. Tanjung Layar Light Beacon Fl(2)5s, in position 02°51'.29N, 104°08'.98E is restored to normal.
  2. Former Notice No. 42(T)\*/22 is cancelled.  
(WGS84)
  3. Charts affected – MAL 635
- .....