

# MAL 6359

91/2007\* Malaysia – Peninsular Malaysia – Tidal Level.

Source : National Hydrographic Center, Royal Malaysia Navy

Chart MAL 6359 (Last Correction NE/2007 ) WGS 84 DATUM

Insert the accompanying block amendments to  
Centre on : 03° 57'. 99N, 103° 25'. 48E

---

107/2007\* Malaysia – Peninsular Malaysia, Pelabuhan Kuantan - Light.

Source : Peninsular Malaysia Marine Department Notice No. 33/2007.

Chart MAL 6359 (Last Correction 91/2007 ) WGS 84 DATUM

Amend range of light, 13m 03° 58'. 59N, 103° 25'. 89E

Insert range of light, 9m 03° 58'. 07N, 103° 26'. 34E

Insert range of light, 9m 03° 58'. 17N, 103° 26'. 52E

---

40/2008\*(T) Peninsular Malaysia, East Coast – Pelabuhan Kuantan – Wrecks

Source : Marine Department Peninsular Malaysia No. 66(T)/2007

Chart MAL 6359 (Last Correction 107/2007) WGS 84 DATUM

Insert  MEISUN G7 03° 57'. 43N, 103°27'.43E

---

101/2008\* Malaysia – East Coast – Pelabuhan Kuantan – Isolated Danger Buoy.

Source : Peninsular Malaysia Marine Department No. 22/2008.

Chart MAL 6359 ( Last Correction 40/2008 ) WGS 84 DATUM

Insert  *F(2)10s* 03° 57'. 9N, 103° 27'. 4E

---

197/2008\* Malaysia – Peninsular Malaysia, East Coast – Approaches to Kuantan Port – Man – of – War Anchorage – Northwards – Light–beacon. Obstruction. Buoy.

Source: British Admiralty Notices No. 5436/2008.

Chart MAL 6359 (Last Correction 101/2008 ) WGS 84 DATUM

Insert  Fl.R.5s17m8M No2 (a) 3° 57'. 06N, 103° 27'. 63E

Delete  *Obstrn*, adjacent to : (a) above

 *Fl.R.5s No 2*, close SSW of : (a) above

---

46/2011\*(T) Malaysia – Peninsular Malaysia, East Coast – Sg. Kuantan – Buoy Missing.

Source: Peninsular Malaysia Marine Department No. 08(T)/2011.

Chart MAL 6359 (Last Correction 197/2008) WGS 84 DATUM

Insert legend, (*Missing*) for  
Sg Kuantan Outer buoy, Fl.G. 10s 03° 47'.22N, 103° 21'.30E

---

70/2011\* Malaysia – Peninsular Malaysia – Kuala Rompin – Sg. Kuantan – Resumed Operations.

Source: Marine Department Peninsular Malaysia Notice No. 21/2011.

Chart MAL 6359 (Last Correction 46/2011(T)) WGS 84 DATUM

Insert Sg Kuantan Outer buoy, Fl.G. 10s 03° 47'.22N, 103° 21'.30E  
Notice No. 46/2011(T) is hereby cancelled.

---

203/2011(T)\* Malaysia – Peninsular Malaysia, East Coast – Approaches to Kuantan Port – Fairway buoy.

Source: National Hydrographic Centre, Royal Malaysian Navy.

Chart MAL 6359 (Last Correction 70/2011) WGS 84 DATUM

Insert legend (*Missing*) for  
Fairway buoy, LFl. 10s 03° 55'.54N, 103° 29'.15E

---

85/2012 Malaysia – East Coast – Kuantan Port – Wreck and Isolated Danger Buoy.

Source: Marine Department Peninsular Malaysia Notice No. 19/2012.

Chart MAL 6359 (Last Correction 203/2011(T)) WGS 84 DATUM

Delete Notice No. 40/2008(T)\* is hereby cancelled 03° 57'.43N, 103° 27'.43E  
Notice No. 101/2008\* is hereby cancelled 03° 57'.90N, 103° 27'.40E

---

168/2012\* Malaysia – Pahang – Sg. Kuantan – Light buoy.

Source: Marine Department Malaysia Notices No 55(T)/2012 .

Chart MAL 6359 (Last Correction 85/2012) WGS 84 DATUM

Amend light to, 5s 03° 47'.30N, 103° 21'.15E

---

49/2013 Malaysia – Pahang – Kuantan Port – Light Beacon.

Source: Marine Department Malaysia No. 16/2013(T).

Chart MAL 6359 (Last Correction 168/2012) WGS 84 DATUM

Delete  No.2  
Fl.R.5s17m8M 03° 57'.06N, 103° 27'.63E

---

**50/2013 Malaysia – Pahang – Kuantan Port Fairway – Resumed Operation.**

**Source: Marine Department Malaysia No. 14/2013.**

Chart MAL 6359 (Last Correction 49/2013) WGS 84 DATUM

**Delete** legend (*Missing*) for  
Fairway buoy, *LFl. 10s* 03° 55'.54N, 103° 29'.15E  
Notice No. 203/2011(T) is hereby cancelled

---

**166/2013(T) Malaysia – Pahang – Kuantan Port – Light Beacon – Light Buoy.**

**Source: Marine Department Malaysia No. 97/2013(T) and No. 100/2013(T).**

Chart MAL 6359 (Last Correction 50/2013) WGS 84 DATUM

**Delete**  No.3, *Fl(2)G.10s14m* 03° 57'.57N, 103° 27'.29E

**Insert**  *No.3*  
*Fl(2)G.10s* 03° 57'.65N, 103° 27'.46E

---

**47/2014 Malaysia - Peninsular Malaysia, East Coast - Kuantan Port N - Works.**

**Source: British Admiralty Notices No. 428/2014.**

Chart MAL 6359 (Last Correction 133/2013(T)) WGS 84 DATUM

**Insert** legend, Works in progress (2013), centred on : 03° 59'.79N, 103° 26'.03E

---

**48/2014(T) Malaysia – Pahang – Sg. Kuantan – Buoy Missing.**

**Source: Marine Department Malaysia No. 9/2014(T).**

Chart MAL 6359 (Last Correction 47/2014) WGS 84 DATUM

**Insert** legend, (*Missing*) for  
Sg Kuantan Outer buoy, *Fl.G.10s* 03° 47'.22N, 103° 21'.30E

---

**45/2015(T) Malaysia - Pahang - Kuantan - Wreck Marking Buoy.**

**Source: Marine Department Malaysia Notice No. 7/2015(T).**

Chart MAL 6359 (Last Correction 48/2014(T)) WGS 84 DATUM

**Insert**  *Fl.Y 5s* 03° 57'.74N, 103° 27'.43E

Chart MAL 645 (Last Correction 132/2014) WGS 84 DATUM

**Insert**  *Fl.Y 5s* 03° 57'.74N, 103° 27'.43E

---

**46/2015(T) Malaysia - Pahang - Kuantan Port - Light Buoy.**

**Source: Marine Department Malaysia No. 9/2015(T).**

Chart MAL 6359 (Last Correction 45/2015(T)) WGS 84 DATUM

**Move**  *No.3*  
*Fl.(2)G.10s* 03° 57'.65N, 103° 27'.46E  
to: 03° 57'.44N, 103° 27'.70E

---

**59/2015(T)\* MALAYSIA - Pahang - Kuantan - Tanjung Gelang - Beacon Unlit.**

**Source: Royal Malaysia Navy.**

Chart MAL 6359 (Last Correction 46/2015(T)) WGS 84 DATUM

**Insert** legend (**Unlit**) for  
Tanjung Gelang, Fl.R.2s 03° 58'.150N, 103° 26'.210E

---

**136/2015 MALAYSIA – Pahang – Pelabuhan Kuantan – Light Beacon.**

**Source: Marine Department Malaysia No. 74/2015.**

Chart MAL 6359 (Last Correction 59/2015) WGS 84 DATUM

**Delete**  *NO.3*  
*Fl(2).G.10s14m* 03° 57'.57N, 103° 27'.29E

---

**77/2016 MALAYSIA – Pahang – Sungai Kuantan – Buoy.**

**Source: Marine Department of Malaysia Notice No. 28/2016.**

Chart MAL 6359 (Last Correction 136/2015) WGS 84 DATUM

**Move**  *FL.G.10s* from: 03° 47'.22N, 103° 21'.30E  
to: 03° 47'.01N, 103° 21'.35E

Notice No. 48/2014(T) is hereby cancelled

---

**95(T)\*/2017 MALAYSIA – Pahang – Tanjung Gelang – Beacons.**

**Source: Royal Malaysia Navy.**

1. Tanjung Gelang Beacon, Fl(4)R.12s9m, in position 03° 58'.05N, 103° 26'.32E and Fl.R, 03° 58'.09N, 103° 26'.09E is reported unlit.
  2. Mariners are advised to navigate with caution in the area.
  3. Charts affected – MAL 6359.
-

**120(P)\*/2017 MALAYSIA – Pahang – Pelabuhan Kuantan – Works.**

**Source: Kuantan Port Consortium Sdn Bhd.**

1. Works are in progress to construct the new jetty and breakwater.
  2. New breakwater have been established in the vicinity of position, 03° 59'.46N, 103° 26'.39E.
  3. The works include extensive changes to the coastline.
  4. The construction area is bounded by the follow positions:
    - (a) 03° 59'.94N, 103° 24'.98E
    - (b) 03° 59'.94N, 103° 26'.87E
    - (c) 03° 58'.39N, 103° 26'.87E
    - (d) 03° 58'.39N, 103° 26'.43E
  5. Mariners are advised to navigate with caution and keep a safe distance. Contact Kuantan Port Authority for the lates information.
  6. These changes will be included on the affected charts where futher information become available.
  7. Chart affected – MAL 6359.
- 

**188\*/2017 MALAYSIA – Kuantan– Tg.Gelang. Beting Layang-Layang – Wreck.**

**Source: National Hydrographic Centre.**

Chart MAL 6359 (Last Correction 120/2017) WGS 84 DATUM

<b>Delete</b>	 <i>RICO Wreck Mast PA</i>	03° 57'.78N,	103° 27'.30E
<b>Insert</b>	 <i>RICO Wk</i>	03° 57'.75N,	103° 27'.28E

---

**31\*/2018 MALAYSIA – Pahang – Pelabuhan Kuantan – Light beacons.**

**Source: Marine Department of Malaysia No. 9/2018.**

Chart MAL 6359 (Last Correction 188/2017) WGS 84 DATUM





<b>Insert</b>	 FI.G.3s11m10M	03° 58'.49N,	103° 26'.76E
	 FI.Y.5s10m5M	03° 58'.92N,	103° 26'.79E

---

**91\*/2018 MALAYSIA – Pahang – Pelabuhan Kuantan – Light beacons.**

**Source: Marine Department of Malaysia No. 81/2017, 38/2018.**

Chart MAL 6359 (Last Correction 31/2018) WGS 84 DATUM

<b>Insert</b>	 FI.G.3s11m	03° 58'.92N,	103° 26'.79E
	 FI.Y.5s10m	03° 58'.49N,	103° 26'.76E
<b>Replace</b>	 FI(4)G.12s9m, with  FI.Y.3s12m	03° 58'.17N,	103° 26'.52E

---

**94(T)\*/2018 MALAYSIA – Pahang – Pelabuhan Kuantan – Light beacon.**

**Source: Marine Department of Malaysia No. 37(T)/2018.**

1. Kuantan Port leading light 311° light beacon, in position 03°58'.58N, 103°25'.90E is temporary unlit.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Charts affected – MAL 6359.
- 

**120(T)\*/2018 MALAYSIA – Pahang – Kuantan Port – Light beacon.**




**Source: Marine Department of Malaysia No. 59(T)/2018.**

1. Kuantan port leading light, 311°04 rear light beacon, OC.G.5s34m, in position 03°58'.94N, 103°25'.50E is temporarily unlit.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Charts affected – MAL 6359.
- 

**129\*/2018 MALAYSIA – Pahang – Kuantan Port – Light beacons.**

**Source: Marine Department of Malaysia No. 63, 72/2018.**

Chart MAL 6359 (Last Correction 120/2018) WGS 84 DATUM

<b>Insert</b>	 Q.G.15m8M KP.5	03° 56'.81N,	103° 28'.44E
	 Q.R.15m8M KP.4	03° 56'.10N,	103° 28'.46E
	 FI(2)G.5s15m8M KP.3	03° 56'.53N,	103° 29'.55E
	 FI(3)R.5s15m8M KP.6	03° 56'.95N,	103° 27'.47E



FI(3)G.5s15m8M  
KP.7



03° 57'.57N, 103° 27'.44E

**154\*/2018 MALAYSIA – Pahang – Kuantan Port – Legend. Light.**

**Source: Marine Department of Malaysia No. 70/2018.**

Chart MAL 6359 (Last Correction 129/2018) WGS 84 DATUM

**Amend** legend to, 311° 14', centred on: 03° 56'.63N, 103° 28'.13E

**Replace**  Q.G.13M, with,  Q.G.12M 03° 58'.59N, 103° 25'.89E

**155\*/2018 MALAYSIA – Pahang – Kuantan Port – Buoys.**

**Source: Marine Department of Malaysia No. 94/2018.**

Chart MAL 6359 (Last Correction 154/2018) WGS 84 DATUM

**Insert**  *Rico wreck*  
*FI(2)5s6M* 03° 57'.81N, 103° 27'.31E

**199\*/2018 MALAYSIA – Pahang – Kuantan Port – Buoys.**

**Source: Marine Department of Malaysia No. 122/2018.**

Chart MAL 6359 (Last Correction 155/2018) WGS 84 DATUM

**Delete**  *No .1*  
*FI.G.5s* 03° 56'.95N, 103° 28'.01E

 *No .3*  
*FI(2)G.10s* 03° 57'.44N, 103° 27'.70E

 *FI.Y.5s* 03° 57'.74N, 103° 27'.43E

**230\*/2018 MALAYSIA – Pahang – Pelabuhan Kuantan – Pilots. Anchorage areas. Legend.**

**Source: Kuantan Port Authority.**

Chart MAL 6359 (Last Correction 199/2018) WGS 84 DATUM





**Insert**  03° 56'.30N, 103° 28'.65E

**Delete**  03° 55'.55N, 103° 29'.40E

**258\*/2018 MALAYSIA – Pahang – Pelabuhan Kuantan – Light beacons.**

**Source: National Hydrographic Centre.**

Chart MAL 6359 (Last Correction 230/2018) WGS 84 DATUM

**Replace**  Fl.G.3s11m with  Fl.Y.5s10m 03° 58'.92N, 103° 26'.79E  
 Fl.Y.5s10m with  Fl.G.3s11m 03° 58'.49N, 103° 26'.76E

**101\*/2019 MALAYSIA – Pahang – Pelabuhan Kuantan – Blocks.**

**Source: National Hydrographic Centre.**

Chart MAL 6359 (Last Correction NE/2018) WGS 84 DATUM

**Insert** the accompanying block, centred on: (a) 03° 59'.34N, 103° 25'.78E  
(b) 03° 58'.23N, 103° 24'.78E

**198\*/2019 MALAYSIA – Pahang – Pelabuhan Kuantan – Light beacon.**

**Source: Marine Department of Malaysia No. 150(T)/2019.**

Chart MAL 6359 (Last Correction 101/2019) WGS 84 DATUM

**Insert** legend, (Ru) 03° 57'.57N, 103° 27'.44E

**221\*/2019 MALAYSIA – Pahang – Pelabuhan Kuantan – Depths.Contours.**

**Source: National Hydrographic Centre.**


Chart MAL 6359 (Last Correction 198/2019) WGS 84 DATUM

**Delete** depth, 15<sub>4</sub>, enclosed by 20m contour 03° 59'.42N, 103° 25'.75E  
depth, 15<sub>4</sub>, enclosed by 20m contour 03° 59'.19N, 103° 25'.87E  
depth, 15, and associated 20m contour SE to enclose 03° 59'.17N, 103° 25'.82E

**84\*/2020 MALAYSIA – Pahang – Kuala Kuantan – Light buoy.**

**Source: Marine Department of Malaysia No. 88/2020.**


Chart MAL 6359 (Last Correction 221/2019) WGS 84 DATUM

**Move**  Fl. Y.5s from: 03° 47'.30N, 103° 21'.15E  
to: 03° 47'.45N, 103° 21'.16E






To accompany Malaysia Notices to Mariner No. 149 of 2020



Block for Chart MAL 6359 (A)

To accompany Malaysia Notices to Mariner No. 149 of 2020



Block for Chart MAL 6359 (B)

**196(T)\*/2020 MALAYSIA – Pahang – Pelabuhan Kuantan – Light Bouy.**

Source: Marine Department of Malaysia No. 285/2020(T).

1. Inner Light Buoy *LFI.10s*, in position 03°55'.52N, 103°29'.15E is temporarily unlit.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Charts affected – MAL 6359.
- 

**197(T)\*/2020 MALAYSIA – Pahang – Sungai Kuantan – Light Bouy.**

Source: Marine Department of Malaysia No. 291/2020(T).

1. Inner Light Buoy *Fl.R.7s*, in position 03°47'.71N, 103°20'.90E is temporarily unlit.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Charts affected – MAL 6359
- 

**206\*/2020 MALAYSIA – Pahang – Tg. Gelang – Buoy.**

Source: Marine Department of Malaysia No. 228/2020.

Chart MAL 6359 (Last Correction 197/2020) WGS 84 DATUM

**Amend** light-buoy to, *Fl(2)10s* 03° 57'.81N, 103° 27'.31E

---

**209\*/2020 MALAYSIA – Pahang – Pelabuhan Kuantan – Light Buoy.**

Source: Marine Department of Malaysia No. 302/2020.

1. Inner Light Buoy *LFI.10s*, in position 03°55'.52N, 103°29'.15E is restored to normal.
  2. Former Notice No. 196/2020(T) is cancelled.
  3. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  4. Charts affected – MAL 6359.
- 

**210\*/2020 MALAYSIA – Pahang – Sungai Kuantan – Light Buoy.**

Source: Marine Department of Malaysia No. 303/2020.

1. Inner Light Buoy *Fl.R.7s*, in position 03°47'.71N, 103°20'.90E is restored to normal.
  2. Former Notice No. 197/2020(T) is cancelled.
  3. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  4. Chart affected – MAL 6359
-

42\*/2021 MALAYSIA – Pahang – Sungai Kuantan – Beacon.

Source: Marine Department of Malaysia No. 32/2021.

Chart MAL 6359 (Last Correction 210/2020) WGS 84 DATUM

Delete



Fl.G.2s10M

03° 48'.58N,

103° 20'.42E

---