

MAL 7150

149/2009*(T) Malaysia – Sarawak – Tanjung Po – Buoy and Beacon.

Source: Sarawak Marine Department No. 60/2009(T) and 63/2009(T).

Chart MAL 7150 (Last Correction 162/2009) WGS 84 DATUM

Insert	legend, (<i>Unlit</i>) for Tanjung Po, Buoy No. 8, Fl.R.4s	01° 38'. 67N,	110° 30'. 50E
	legend, (<i>Unlit</i>) for Muara Tebas, Beacon No.1, Fl.6s9M	01° 39'. 00N,	110° 29'. 68E

166/2009*(T) Malaysia – Sarawak – Tanjung Po – Buoy.

Source: Sarawak Marine Department No. 69/2009(T).

Chart MAL 7150 (Last Correction 149(T)/2009) WGS 84 DATUM

Insert	legend, (<i>Unlit</i>) for Tanjung Po, Buoy No. 2, Fl.R.4s	01° 42'. 40N,	110° 33'. 49E
--------	---	---------------	---------------

44/2010* Malaysia – Sarawak – Tanjung Po – Buoy – Resumed.

Source: Sarawak Marine Department No. 8/2010.

Chart MAL 7150 (Last Correction 166(T)/2009) WGS 84 DATUM

Tanjung Po, Buoy No. 2, Fl.R.4s Cancel Notice No. 166/2009(T).	01°42'.40N,	110°33'.49E
Tanjung Po, Buoy No. 8, Fl.R.4s Cancel Notice No. 149/2009(T).	01°38'.67N,	110°30'.50E

189/2010* Malaysia – Sungai Sarawak – Senari Port – Buoy.

Source: Sarawak Marine Department No. 60/2010

Chart MAL 7150 (Last Correction 44/2010) WGS 84 DATUM

Delete	 Q(9)15s	01° 37'.38N,	110° 27'.51E
--------	---	--------------	--------------

38/2011* Malaysia – Sarawak – Sungai Sarawak – McDougall Point North-westwards – Wreck.

Source: British Admiralty Notices No. 0083/2011.

Chart MAL 7150 (Last Correction 189/2010) WGS 84 DATUM

Delete		01° 37'.35N,	110° 27'.56E
--------	---	--------------	--------------

100/2011 (T)* Malaysia – Sarawak – Tanjung Po – Lighthouse.

Source: Sarawak Marine Department No. 34/2011(T).

Chart MAL 7150 (Last Correction 38/2011) WGS 84 DATUM

Amend	range of light to, 18M	01° 43'.48N,	110° 31'.43E
--------------	------------------------	--------------	--------------

169/2011(T)* Malaysia – Sarawak – Tanjung Po – Buoy and Beacon.

Source: Sarawak Marine Department No. 62/2011(T).

Chart MAL 7150 (Last Correction 100/2011(T)) WGS 84 DATUM

Insert	legend, (<i>Unlit</i>) for Tanjung Po, Buoy No. 8, Fl.R.4s	01° 38'.67N,	110° 30'.50E
---------------	---	--------------	--------------

63/2012(T) Malaysia – Sarawak – Tanjung Po – Buoys.

Source: Sarawak Marine Department No. 11/2011(T).

Chart MAL 7150 (Last Correction 169/2012(T)) WGS 84 DATUM

Insert	legend (<i>Out Of Position</i>) for Port Hand Buoy No. 8, Fl.R.4s	01° 38'.66N,	110° 30'.50E
---------------	--	--------------	--------------

**74/2012 Malaysia – Sarawak – Sungai Sarawak – Tanjung Po to Tanjung Bako – Depths.
Drying height.**

Source: British Admiralty Notices No. 786(P)/2012.

Chart MAL 7150 (Last Correction 63/2012(T)) WGS 84 DATUM

Insert	depth 52	01° 41'.58N,	110° 32'.76E
	depth 6	01° 40'.29N,	110° 32'.05E
	depth 43	01° 38'.92N,	110° 30'.60E
	depth 61	01° 38'.52N,	110° 29'.57E
	depth 7	01° 37'.81N,	110° 27'.71E
	depth 55	01° 37'.11N,	110° 27'.15E
	depth 68	01° 37'.06N,	110° 27'.42E

86/2012 Malaysia – Sarawak – Tanjung Po – Buoy – Resumed operations.

Source: Sarawak Marine Department No. 14/2012.

Chart MAL 7150 (Last Correction 74/2012) WGS 84 DATUM

Insert	Tanjung Po, Buoy No. 8, Fl.R.4s Notice No. 169/2011(T)* is hereby cancelled	01° 38'.67N,	110° 30'.50E
---------------	--	--------------	--------------

193/2012 Malaysia – Sarawak – Tanjung Po – Buoy.

Source : Sarawak Marine Department No. 61/2012.

Chart MAL 7150 (Last Correction 86/2012) WGS 84 DATUM

Insert		<i>Fl.G.4s</i> <i>No.1</i>	02° 42'.41N,	110° 32'.84E
---------------	---	-------------------------------	--------------	--------------

38/2013 Corrigendum Notices to Mariners 12 of 2012.

Amend Notices No. 193/2012

Chart MAL 7150 (Last Correction 193/2012) WGS 84 DATUM

Insert		<i>Fl.G.4s</i> <i>No.1</i>	02° 42'.41N,	110° 32'.84E
	to:		01° 42'.41N,	110° 32'.84E

39/2013 Malaysia – Sarawak – Tanjung Po – Resumed Operation – Buoys.

Source: Sarawak Marine Department No. 2/2013 And Sarawak List Of Lights.

Chart MAL 7150 (Last Correction 38/2013) WGS 84 DATUM

Delete		<i>Fl(2).6s</i> <i>No.3</i>	01° 42'.55N,	110° 33'.05E
---------------	---	--------------------------------	--------------	--------------

Insert		<i>Fl.G.4s</i> <i>No.3</i>	01° 40'.82N,	110° 32'.16E
---------------	---	-------------------------------	--------------	--------------

Move		<i>Fl.R.4s</i> <i>No.4</i>	01° 40'.60N,	110° 32'.52E
	to:		01° 40'.55N,	110° 32'.65E

Move		<i>Fl.G.4s</i> <i>No.5</i>	01° 40'.84N,	110° 32'.08E
	to:		01° 39'.51N,	110° 31'.24E

Move		<i>Fl.R.4s</i> <i>No.6</i>	01° 39'.26N,	110° 31'.74E
	to:		01° 39'.20N,	110° 31'.76E

Move		<i>Fl.G.4s</i> <i>No.7</i>	01° 39'.50N,	110° 31'.30E
	to:		01° 39'.03N,	110° 30'.39E

Insert		<i>Batu Tjong</i> <i>Fl.(2)6s</i>	01° 38'.87N,	110° 30'.22E
---------------	---	--------------------------------------	--------------	--------------

Delete legend (*Out Of Position*) for
Port Hand Buoy No. 8, Fl.R.4s 01° 38'.66N, 110° 30'.50E
Notice No. 63/2012(T) is hereby cancelled

105/2013 **Malaysia – Sarawak – Sungai Sarawak – Tanjung Embang – Light- beacon.**
Source : Sarawak Marine Department No. 56/2009.

Chart MAL 7150 (Last Correction 39/2013) WGS 84 DATUM

Amend light to, Fl.3s30m8M 01° 37'.13N, 110° 30'.29E

114/2013(T) **Malaysia – Sarawak – Tanjung Po – Buoy.**

Source: Sarawak Marine Department No. 47/2011(T).

Chart MAL 7150 (Last Correction 105/2013) WGS 84 DATUM

Move  Fl.R.4s 01° 42'.40N, 110° 33'.49E
No.2

to: 01° 42'.91N, 110° 33'.86E

49/2014 **Malaysia – Sarawak – Sungai Sarawak – Tanjung Embang – Light - beacon.**

Source: Sarawak Marine Department No. 9/2014.

Chart MAL 7150 (Last Correction 114/2013(T)) WGS 84 DATUM

Amend light to, Fl.3s21m8M 01° 37'.34N, 110° 30'.50E

57/2014 **Malaysia - Sarawak - Tanjung Baram to Tanjung Datu - Automatic Identification Systems. Anchorage area. Pilot boarding place.**

Source: British Admiralty Notices No. 1251/2014.

Chart MAL 7150 (Last Correction 49/2014) WGS 84 DATUM

Insert  at light 01° 43'.48N, 110° 31'.43E

202/2015 **MALAYSIA – Sarawak – Tanjung Patong, Tanjung Sirik, Tanjung Sirik(i),
Batuan Likau and Kuala Baram – Light Beacon .**

Source : Sarawak Marine Department No. 102/2015*.

Chart MAL 7150 (Last Correction 57/2014) WGS 84 DATUM

Insert  Fl.(2) Y. 5s 15m 5M 01° 45'.22N, 110° 30'.13E

90*/2017 MALAYSIA – Sarawak – Muara Tebas – Buoys.

Source: Sarawak Marine Department No. 51/2017*.

Chart MAL 7150 (Last Correction 202/2015) WGS 84 DATUM

Insert  *Fl.Y(5)10s*
Buoy 1 01° 38'.67N, 110° 29'.63E

 *Fl.Y(5)10s*
Buoy 2 01° 38'.26N, 110° 28'.33E

29*/2018 MALAYSIA – South China Sea – Kuching-Bintulu – Submarine cable.

Source: Telekom Malaysia Berhad.

Chart MAL 7150 (Last Correction 90/2017) WGS 84 DATUM

Insert submarine cable, , joining: 01° 47'.63N 110° 26'.72E (W border)
01° 49'.28N 110° 27'.69E
01° 50'.26N 110° 27'.95E (N border)

121(T)*/2018 MALAYSIA – Sarawak – Tanjung Po – Buoy.

Source: Sarawak Marine Department No. 23(T)/2018.

1. Tanjung Po, Buoy No. 2, *Fl.R.4s*, is out of position. The details are as follows:
(a) Charted actual position: 01°42'.91N, 110°33'.86E.
(b) Current Location: 01°50'.66N, 110°40'.16E.
2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
3. Charts affected – MAL 7150.

37*/2019 MALAYSIA – Sarawak – Tanjung Bako and Tg. Batu – Beacon.

Source: Sarawak Marine Department No. *01/2019.

Chart MAL 7150 (Last Correction 121/2018) WGS 84 DATUM

Delete  Q.G.5M
No.2 01° 37'.90N, 110° 27'.82E

Insert  Q.G.5M
No.2 01° 37'.89N, 110° 27'.83E

241*/2019 MALAYSIA – Sarawak – Sungai Sarawak – Buoy.

Source: Sarawak Marine Department No. 123(P)/2019.

Chart MAL 7150 (Last Correction 37/2019) WGS 84 DATUM

Insert legend, (Ru) 01° 38'.26N, 110° 28'.33E

137(T)*/2020 MALAYSIA – Sarawak – Tanjung Po – Buoy.

Source: Sarawak Marine Department No. 73(T)/2020.

1. Buoy No. 1, *Fl.G.4s*, in position 01°42'.41N, 110°32'.84E and Buoy No. 2, *Fl.R.4s*, in position 01°42'.91N, 110°33'.86E is off station.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 7150.
-

190(T)*/2020 MALAYSIA – Sarawak – Tanjung Po – Buoy.

Source: Sarawak Marine Department No. 111/2020(T).

1. Buoy No.5 *Fl.G.4s*, in position 01°39'.52N, 110°31'.23E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 7150.
-