

# MAL 723

**39(T)\*/2019 MALAYSIA – Sarawak – Kuala Santubong – Light buoys.**

**Source: Sarawak Marine Department No. 149(T)/2018.**

Chart MAL 723 (Last Correction NE/2018) WGS 84 DATUM

<b>Insert</b>		<i>Fl(2)10s</i>	01° 45'.08N,	110° 16'.32E
		<i>Fl(2)10s</i>	01° 45'.32N,	110° 17'.45E

---

**57\*/2019 MALAYSIA – Sarawak – Tanjung Datu – Wreck.**

**Source: Sarawak Marine Department No. 14(T)/2019.**

Chart MAL 723 (Last Correction 39/2019) WGS 84 DATUM

<b>Insert</b>		<i>REP (2019)</i> <i>PA</i>	02° 14'.06N,	109° 51'.00E
---------------	---	--------------------------------	--------------	--------------

---

**205(T)\*/2019 MALAYSIA – Sarawak – Kuala Santubong – Light buoys.**

**Source: Sarawak Marine Department No. 77(T)/2019.**

1. Song Kian Baru light buoy, *Fl(2)10s*, in position 01°45'.08N, 110°16'.33E and Michelle light buoy, *Fl(2)10s*, in position 01°45'.33N, 110°17'.45E are missing.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Charts affected – MAL 723.
- 

**172(T)\*/2020 MALAYSIA – Sarawak – Tanjung Sipang – Beacon.**

**Source: Sarawak Marine Department No. 103/2020(T).**

1. Beacon Fl.7.5s18M, in position 01°48'.35N, 110°20'.14E is temporarily unlit.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Charts affected – MAL 723.
-