

73(T)*/2021 MALAYSIA – Sabah – Terusan Tando Bulong – Beacons.

Source: Royal Malaysian Navy.

1. Beacon P4 and Beacon No.9 Fl.5s5m5M, in position 04°24'.24N, 118°35'.98E and 04°24'.22N, 118°36'.50E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 8433.
-