

**74(T)\*/2021      MALAYSIA – Sabah – Terusan Tando Bulong – Buoy.**

**Source: Royal Malaysian Navy.**

1. Buoy *Fl* 5s, in position 04°24'.58N, 118°35'.88E is missing.

2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)

3. Charts affected – MAL 8433.

.....