NATIONAL HYDROGRAPHIC CENTRE Royal Malaysian Navy



MALAYSIAN NOTICES TO MARINERS

Monthly Edition 6 of 2014 30 JUNE 2014

CONTENTS

I - Explanatory Notes / Index of Charts Affected.

II - Notices to Mariners and Corrections to Charts.

III - Marine Safety Information.

IV - Corrections to Malaysian List of Lights.

Mariners are requested to inform The Hydrographer, National Hydrographic Centre, Bandar Armada Putra, Pulau Indah, 42009 PORT KLANG, Selangor Darul Ehsan, Malaysia. (Tel: +603 3169 4400), (Fax: +603 3101 3111), E-mail: nhc@hydro.gov.my immediately of the discovery of new dangers, changes or defects in aids to navigation and shortcoming in Malaysian charts or publications.

DATO' PAHLAWAN ZAAIM BIN HASAN Rear Admiral The Hydrographer



SECTION I

EXPLANATORY NOTES

structions for the correction of Malaysian Chart (MAL) while notices in Section in give information on manne safety information. Geographical positions refer to the largest scale chart unless otherwise stated. Bearing are true reckoned clockwise from 000 to 359, those relating to lights are from seaward.

Notices to Mariners correcting MAL charts are issued by the National Hydrographic Centre, Royal Malaysian Navy and should be inserted on the charts affected in waterproof violet ink in case of permanent notices and in pencil in case of temporary notices.

Temporary and Preliminary Notices

These are indicated by (T) or (P) after the notice number.

Original Information

An asterisk (*) adjacent to the number of a notice indicates that the notice is based on original information.

Malaysian Notice (MN)

Mariners are to take note the legend MN indicates Malaysian Notice.

INDEX OF CHARTS AFFECTED			
MAL 5	88/2014, 95/2014(T), 96/2014(T), 97/2014(T)	MAL 645	97/2014(T)
MAL 515	89/2014	MAL 65	95/2014(T), 97/2014(T)
MAL 532	90/2014(T)	MAL 655	88/2014, 96/2014(T), 97/2014(T)
MAL 54	90/2014(T)	MAL 68	88/2014, 96/2014(T)
MAL 5622	91/2014	MAL 750	93/2014, 99/2014(T)
MAL 58	92/2014	MAL 751	93/2014, 99/2014(T)
MAL 6	93/2014, 98/2014(T), 99/2014(T), 100/2014(T)	MAL 754	99/2014(T)
MAL 6134	94/2014	MAL 762	93/2014, 99/2014(T), 100/2014(T)
MAL 625	95/2014(T)	MAL 781	100/2014(T)
MAL 635	95/2014(T)	MAL 864	99/2014(T)

Your complimentary use period has ended. Thank you for using PDF Complete.

SECTION II

dor Field - Offshore installations.

ces No. 2639/2014.

/2014) WGS 84 DATUM Cendor Insert 104° 35q10E 05° 34q10N, 05° 35'.00N. 104° 34′.70E 03° 35'.40N, 104° 33'.70E **Delete** Cendor, close N of: (a) above Chart MAL 655 (Last Correction 64/2014) WGS 84 DATUM Insert Cendor (a) 05° 34q10N, 104° 35q10E 05° 35'.00N, 104° 34′.70E 03° 35′.40N, 104° 33'.70E **Delete** Cendor, close N of: (a) above Chart MAL 68 (Last Correction 84/2014) WGS 84 DATUM Insert Cendor 05° 34q10N, 104° 35q10E 05° 35'.00N, 104° 34'.70E 104° 33'.70E 03° 35′.40N, **Delete** Cendor, close N of: (a) above 89/2014* Malaysia - Johor - Selat Singapura - Buoy - Missing. Source: Hydrographic Note H.102 from DZV Kreuz Installer dated 24 May 14. Chart MAL 515 (Last Correction 66/2014) WGS 84 DATUM Insert legend, (*Missing*) for 01° 17a67N. 104° 11a10E Bouy, Fl.(2)10s 90/2014(T) Malaysia - Selangor - Kuala Langat - Light Beacon. Source: Marine Department Malaysia No. 48/2014(T). Chart MAL 532 (Last Correction 67/2014) WGS 84 DATUM FI.G.5s4m8M **Delete** 02° 48′.07N, 101° 24'.10E

7/2014) WGS 84 DATUM

02° 48′.07N,

101° 24'.10E

Inlimited Pages and Expanded Features

gkawi - Light Buoys - Unlit.

Source: KD GANYANG, Royal Malaysian Navy.

Chart MAL 5622 (Last Correction 182/2013) WGS 84 DATUM

Insert legend, (*Unlit*) for

Bouy Jerkom 1, FL.R.5s 06° 15q30N, 099° 45q54E

legend, (Unlit) for

Bouy Jerkom 2, FL (2+1).R.12s 06° 15q64N, 099° 45q89E

.....

92/2014 Thailand - West Coast - Ko Phiphi Don S - Wreck.

Source: British Admiralty Notices No. 2711/2014.

Chart MAL 58 (Last Correction 180/2013) WGS 84 DATUM

Insert ## Rep(2014) 07° 41'.70N, 98° 46'.60E

93/2014 Malaysia - Sarawak - Central Luconia Gas Field NE - Submarine pipeline. Legend.

Source: British Admiralty Notices No. 2288/2014.

Chart MAL 6 (Last Correction 83/2014) WGS 84 DATUM

Insert submarine pipeline, → → → joining: 04° 31'.82N, 113° 03'.70E (□)

04° 43′.53N, 113° 06′.20E (⊡)

Chart MAL 750 (Last Correction 73/2014) WGS 84 DATUM

Insert submarine pipeline, → → → joining: (a) 04° 31'.82N, 113° 03'.70E (□)

(b) 04° 43'.53N, 113° 06'.20E (•)

Legend, Gas (see Note), along: (a) - (b) above

Chart MAL 751 (Last Correction 69/2014) WGS 84 DATUM

Insert submarine pipeline, → → → joining: (a) 04° 31'.82N, 113° 03'.70E (□)

(b) 04° 43′.53N, 113° 06′.20E (□)

Legend, Gas (see Note), along: (a) - (b) above



Your complimentary use period has ended.
Thank you for using PDF Complete.

55/2014) WGS 84 DATUM

→ joining: (a) 04° 31′.82N, 113° 03′.70E (□)

(b) 04° 43'.53N, 113° 06'.20E (•)

Unlimited Pages and Expanded Features

Legend, Gas (see Note), along: (a) - (b) above

94/2014 Singapore - Temasek Fairway W, West Jurong Channel and Kuala Johor - Light. Works. Mooring buoys.

Source: British Admiralty Notices No. 2502/2014.

Chart MAL 6134 (Last Correction 41/2014) WGS 84 DATUM

Delete FI.Y.6s (sync) TK-MB5 01° 22'.44N, 104° 02'.17E

FI .Y.6s (sync) TK-MB6 01° 22'.56N, 104° 02'.03E

Your complimentary use period has ended. Thank you for using PDF Complete.

SECTION III

ARINE SAFETY INFORMATION buth China Sea - New Built Derrick.

Initial Pages and Expanded Features

pleum dated 2 June 2014.

1. A NEW BUILT DERRICK AND DEEP WATER PIPE LAY VESSEL SK 1200 WILL BE PERFORMING ITS PIPE LAY AS MENTIONED AT POSITION 02 46.00N 104 36.50E STARTED FROM 18 JULY UNTIL 30 JULY 2014.

2. THE VESSELS INVOLVED ARE FOLLOWS:

A. VESSEL : SAPURA KENCANA 1200.

B. FLAG : PANAMA. C. IMO NUMBER : 9651199.

3. MARINERS ARE ADVISED TO NAVIGATE WITH CAUTION WHEN IN THE VICINITY.

4. CHARTS AFFECTED : MAL 5, MAL 65, MAL 625 AND MAL 635.

.....

96/2014(T) Malaysia - Terengganu - South China Sea - New Fpso.

Source: Marine Department Malaysia No. 20/2014(T).

1. A NEW FPSO ESTABLISHED IN AREA OF SOUTH CHINA SEA, OFFSHORE TERENGGANU AT POSITION 05 34.07N 104 35.07E STARTING FROM 01 APR 2014 UNTIL 01 APR 2024 (10 YEARS).

2. DETAILS OF THE VESSEL ARE AS FOLLOWS:

A. VESSEL NAME : FPSO CENDOR.

B. CALL SIGN : 9MLO7.
 C. IMO NUMBER : 8818910.
 D. OFFICIAL NUMBER : 334299.
 E. GROSS TONNAGE : 58745.

F. PORT OF REGISTRY: PORT KLANG.
G. OWNER: MISC BERHAD.

MARINERS ARE ADVISED TO NAVIGATE WITH CAUTION WHEN IN THE VICINITY.

4. CHART AFFECTED : MAL 5, MAL 68 AND MAL 655.

TO THE COTE OF THE CONTROL OF THE COO.

97/2014(T) Malaysia - Terengganu - South China Sea - Drilling Operation.

Source: Marine Department Malaysia No. 49/2014(T).

- 1. THE DRILLING OPERATION IS CURRENTLY BEING CARRIED OUT IN AREA OF TEMBAKAU 2, SOUTH CHINA SEA AT POSITION 04 34.04N 104 30.85E STARTED FROM 15 JUNE UNTIL 30 AUG 2014 (70 DAYS).
- 2. THE VESSELS INVOLVED ARE FOLLOWS:

A. DRILLING VESSEL : WEST PROSPERO

B. SUPPORTING VESSELS : SEA EAGLE 1, JAYA DEFENDER

AND MV FOS LEO.

3. MARINERS ARE ADVISED TO NAVIGATE WITH CAUTION AND KEEP CLEAR WITH MINIMAL DISTANCE OF 2KM RADIUS FROM THE DRILLING AREA.

4. CHARTS AFFECTED : MAL 5, MAL 65, MAL 645 AND MAL 655.



Your complimentary)rilling Operation. use period has ended. Thank you for using PDF Complete.

rtment No. 67/2014(T).

HD. IS SCHEDULED TO CONDUCT AN EXPLORATION DRILLING HORE SARAWAK AT POSITION 04 08.38N 111 54.56E STARTING OF 38 DAYS.

THE DETALIS OF THE DRILLING RIG ARE AS FOLLOWS:

VESSEL NAGA . 1. B. FLAG PANAMA. C. LENGTH 101 M D. BREADTH 67 M

CONTRACTOR: UMW JDC DRILLING SDN. BHD.

- MARINERS ARE ADVISED TO NAVIGATE WITH EXTRA CAUTION AND KEEP CLEAR WITH 2KM AWAY FROM THE DRILLING AREA.
- CHARTS AFFECTED : MAL 6.

99/2014(T) Malaysia - Sarawak - Drilling Rig.

Source: Sarawak Marine Department No. 57/2014(T).

- THE SEMI SUB DRILLING RIG ÆKD ALLIANCEQWAS BEING MOVED FROM LABUAN ANCHORAGE TO F14DR - A WELL LOCATION, OFFSHORE SARAWAK STARTED FROM 01 JUN.
- THE RIG EXPECTED TO BE AT WELL LOCATION FOR A PERIOD APPROXIMATELY 102 DAYS. THE COORDINATES ARE AS FOLLOWS:

A. LABUAN ANCHORAGE 05 11.00N 115 16.70E F14DR - A 04 56.89N 112 31.70E B.

- MARINERS ARE ADVISED TO NAVIGATE WITH EXTRA CAUTION AND KEEP CLEAR WITH 5 NM AWAY FROM THE LOCATIONS WHEN IN THE VICINITY.
- CHARTS AFFECTED : MAL 6, MAL 750, MAL 751, MAL 754, MAL 762 AND MAL 864.

100/2014(T) Malaysia - Sarawak - Drilling Rig.

Source: Sarawak Marine Department No. 69/2014(T).

- THE SEMI SUB DP DRILLING RIG ENSCO 8504qWAS BEING MOVED FROM MARJORAM - 1 WELL LOCATION, OFFSHORE SARAWAK STARTED 1 JUL TO PROPOSE WELL LOCATION AT GUMUSUT DRILL CENTRE - E, OFFSHORE SABAH.
- THE RIG EXPECTED TO BE AT WELL LOCATION FOR A PERIOD APPROXIMATELY 122. DAYS. THE COORDINATES ARE AS FOLLOWS:

A. MARJORAM - 1 05 19.43N 112 50.78E PROPOSED WELL LOCATION 1 05 47.10N 114 20.27E B. PROPOSED WELL LOCATION 1 05 47.08N 114 20.28E

- MARINERS ARE ADVISED TO KEEP CLEAR WITH 5 NM AWAY FROM THE LOCATIONS WHEN IN THE VICINITY.
- CHARTS AFFECTED : MAL 6, MAL 762 AND MAL 781.



SECTION IV CORRECTIONS TO MALAYSIAN LIST OF LIGHTS

-NIL-