

MAL 5152

54*/2019 MALAYSIA – Johor – Permatang Alur Mudah – Obstructions and Wrecks.

Source: National Hydrographic Centre.

Chart MAL 5152 (Last Correction NC/2017) WGS 84 DATUM

Insert	(30) <i>Obstn</i>	01° 38'.35N, 102° 59'.19E
	(12₅) <i>Obstn</i>	01° 35'.88N, 102° 58'.88E
	(9) <i>Obstn</i>	01° 37'.21N, 102° 57'.15E
	(32₅) <i>Obstn</i>	01° 38'.14N, 102° 57'.44E
	(21₅) <i>Obstn</i>	01° 40'.08N, 102° 53'.18E

157(T)*/2019 MALAYSIA – Johor – Tg. Segenting – Lighthouse.

Source: Marine Department of Malaysia No. 110(T)/2019.

1. Bukit Segenting lighthouse, in position 01°47'.50N, 102°53'.40E is temporarily operating on reduced power and light nominal range is reduced to 15M.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 5152.
-

47*/2020 MALAYSIA – Johor – Tg. Segenting – Lighthouse.

Source: Marine Department of Malaysia No. 27/2020.

1. Bukit Segenting lighthouse, in position 01°47'.50N, 102°53'.40E is restored to normal.
 2. Former Notice No. 157/2019(T) is cancelled.
 3. Charts affected – MAL 5152.
-