

107*/2022 MALAYSIA – Melaka – Kuala Linggi – Light Buoy.

Source: Marine Department of Malaysia No. 95/2022.

1. Kuala Linggi Light Buoy *Fl(2)10s*, in position 02°19'.42N, 101°57'.63E is restored to normal.
 2. Former Notice No. 58(T)*/22 is cancelled.
(WGS84)
 3. Chart affected – MAL 532
-