

MAL 5416

141/2016 MALAYSIA – Perak – Tg. Batu Putih – Buoy.

Source: Royal Malaysian Navy.

Chart MAL 5416 (Last Correction NE/2015) WGS 84 DATUM

Amend  *Fl(2)5s* with  (Ru) 04° 14'.42N, 100° 35'.24E

178/2016(T) MALAYSIA – Perak – Selat Manjung (Dinding) – Light Beacon – Unlit.

Source: Marine Department of Malaysia Notice No. 82/2016(T).

Chart MAL 5416 (Last Correction 141/2016) WGS 84 DATUM

Insert legend, (*Unlit*) for
Dinding Bn, *Fl(2)G.5s6M* 04° 14'.68N, 100° 34'.88E

179/2016(T) MALAYSIA – Perak – Selat Manjung (Dinding) – Light Beacon – Unlit.

Source: Marine Department of Malaysia Notice No. 83/2016(T).

Chart MAL 5416 (Last Correction 178/2016) WGS 84 DATUM

Insert legend, (*Unlit*) for
River Rk, *Fl.WRG.3s8m7-4M* 04° 14'.57N, 100° 35'.32E

129*/2017 Malaysia – Perak – Sungai Manjung (Dinding) – Light.

Source: National Hydrographic Centre.

Chart MAL 5416 (Last Correction 179/2016) WGS 84 DATUM

Amend light to, *Fl(3)20s9m8M* Lumut Front 04° 14'.10N, 100° 37'.59E

151*/2017 Malaysia – Perak – Sungai Manjung (Dinding) – Tidal streams. Light.

Source: National Hydrographic Centre.

Chart MAL 5416 (Last Correction 129/2017) WGS 84 DATUM

Insert the accompanying block, *Tidal Streams*
centred on: 04° 14'.20N, 100° 39'.45E



04° 14'.77N, 100° 38'.82E

163(T)*/2018 MALAYSIA – Perak – Tg. Batu Putih – Light buoy.

Source: Marine Department of Malaysia No. 84(T)/2018.

1. Dinding Light buoy, Q.G, in position 04°15'.00N, 100°35'.42E is off station.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 5416 – MAL 5419 – MAL 5425.
-

33*/2019 MALAYSIA – Perak – Sungai Manjung (Dinding) – Blocks.

Source: National Hydrographic Centre.

Chart MAL 5416 (Last Correction 163/2018) WGS 84 DATUM

Insert	the accompanying block, centred on:	(a) 04° 14'.52N,	100° 35'.34E
		(b) 04° 14'.26N,	100° 36'.76E
		(c) 04° 14'.37N,	100° 38'.34E
		(d) 04° 13'.51N,	100° 39'.43E

.....

127(T)*/2019 MALAYSIA – Perak – NE Kg. Teluk Gedung – Buoy.

Source: Royal Malaysian Navy.

1. Selat 2R, *Fl.R.*3s, in position 04°15'.13N, 100°34'.71E is temporarily unlit.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 5416 – MAL 5419 – MAL 5425.
-

163(T)*/2018 MALAYSIA – Perak – Tg. Batu Putih – Light buoy.

Source: Marine Department of Malaysia No. 84(T)/2018.

1. Dinding Light buoy, Q.G, in position 04°15'.00N, 100°35'.42E is off station.
2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
3. Charts affected – MAL 5416.

33*/2019 MALAYSIA – Perak – Sungai Manjung (Dinding) – Blocks.

Source: National Hydrographic Centre.

Chart MAL 5416 (Last Correction 163/2018) WGS 84 DATUM

Insert the accompanying block, centred on:

- (a) 04° 14'.52N, 100° 35'.34E
- (b) 04° 14'.26N, 100° 36'.76E
- (c) 04° 14'.37N, 100° 38'.34E
- (d) 04° 13'.51N, 100° 39'.43E

127(T)*/2019 MALAYSIA – Perak – NE Kg. Teluk Gedung – Buoy.

Source: Royal Malaysian Navy.

1. Selat 2R, *Fl.R.3s*, in position 04°15'.13N, 100°34'.71E is temporarily unlit.
2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
3. Charts affected – MAL 5416.