

**154(T)\*/2022 MALAYSIA – Pulau Langkawi – P.Enggang – Buoys.**

**Source: KD PERANTAU.**

1. Bouy Enggang 1Y *Fl.Y10s* and Enggang 2Y *Fl(4)Y.10s*, in position 06°14'.20N, 099°53'.40E and 06°15'.00N, 099°53'.50E is missing.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Charts affected – MAL 5622
-