

155(T)*/2022 MALAYSIA – Pulau Langkawi – Pelabuhan Kuah, Teluk Sambar – Beacon and Buoy.

Source: KD PERANTAU.

1. Beacon Fl.G.5s5m5M and bouy Fl.Y.5s, in position 06°17'.60N, 099°51'.05E and 06°18'.18N, 099°50'.88E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 5622 .
-