

**35(T)\*/2024      MALAYSIA – Sarawak – Tanjung Po – Buoy.**

**Source: Sarawak Marine Department No. 14(T)/2024.**

1. Bouy No.6, *Fl.R.5s*, in position 01°42'.31N, 110°33'.37E is missing.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Chart affected – MAL 7150.
-