

51*/2023 MALAYSIA – Sarawak – Tanjung Po – Buoy.

Source: Sarawak Marine Department No. 33(T)/2023.

1. Buoy No. 5, *Fl.G.5s*, in position 01°42'.32N, 110°33'.04E is restored to normal.
 2. Former Notice No. 39(T)*/23 is cancelled.
(WGS84)
 3. Charts affected – MAL 7150.
-