

52(T)*/2023 MALAYSIA – Sarawak – Tanjung Po – Buoy.

Source: Sarawak Marine Department No. 39(T)/2023.

1. Buoy No. 2, *Fl.R.5s*, in position 01°48'.17N, 110°30'.98E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 7150.
-