

69(T)*/2024 MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoy.

Source: Sarawak Marine Department No. 31(T)/2024.

1. No. 11 buoy, *Fl.G.5s*, in position 03°15'.52N, 113°02'.57E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Chart affected – MAL 7317.
-