

123*/2022 MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoy.

Source: Sarawak Marine Department No. 98/2022.

1. Pelabuhan Bintulu, Buoy Y5 *Fl.Y.5s*, in position 03°15'.97N, 113°03'.84E is restored to normal.
 2. Former Notice No. 80(T)*/22 is cancelled.
(WGS84)
 3. Chart affected – MAL 7317
-