124*/2022 MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoy.

Source: Sarawak Marine Department No. 97/2022.

- 1. Pelabuhan Bintulu, Buoy C, Fl.G.5s, in position 03°15'.54N, 113°00'.58E is restored to normal.
- 2. Former Notice No. 235(T)*/18 is cancelled. (WGS84)

3. Chart affected – MAL 7317	