

36(T)*/2024 MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoy.

Source: Sarawak Marine Department No. 6(T)/2024.

1. Starboard - Hand Buoy, *Fl.G.4s*, in position 03°11'.10N, 113°01'.66E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Chart affected – MAL 7332.
-