

201*/2021 MALAYSIA – Sarawak – Pelabuhan Bintulu – Light Buoy.

Source: Sarawak Marine Department No. 165/2021(T).

1. Bintulu Port Buoy No. 5, *Fl.G.5s*, in position 03°15'.82N, 113°01'.21E is restored to normal.
 2. Former Notice No. 178(T)*/2021 is cancelled.
(WGS84 DATUM)
 3. Charts affected – MAL 7332
-