

124*/2022 MALAYSIA – Sarawak – Pelabuhan Bintulu – Buoy.

Source: Sarawak Marine Department No. 97/2022.

1. Pelabuhan Bintulu, Buoy C, *Fl.G.5s*, in position 03°15'.54N, 113°00'.58E is restored to normal.
 2. Former Notice No. 235(T)*/18 is cancelled.
(WGS84)
 3. Chart affected – MAL 7332.
-