

189*/2023 MALAYSIA – Sarawak – Tg. Similajau – Buoy.

Source: Sarawak Marine Department No. 149/2023.

1. Racon buoy *Fl.5s*, in position 03°38'.04N, 113°15'.37E is restored to normal.
 2. Former Notice No. 189(T)*/22 is cancelled.
(WGS84
 3. Chart affected – MAL 741.
-