

**79(T)\*/2021      MALAYSIA – Sabah – Terusan Tando Bulong – Buoy.**

**Source: Royal Malaysian Navy.**

1. Buoy *Fl. 10s*, in position 04°23'.48N, 118°36'.27E is unlit.
2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
3. Charts affected – MAL 8434.

.....