

151(T)*/2022 MALAYSIA – Sabah – Teluk Sepangar – Buoys.

Source: Sabah Ports and Harbours Department No. 08/2022.

1. Temporary Bouy for Teluk Sepangar Port Development Installed 20 Oct to 25 Nov 22 :



PB1

06° 04'.41N, 116° 06'.26E



PB2

06° 04'.87N, 116° 06'.77E



PB2

06° 05'.12N, 116° 07'.09E



TMB-RD-1

06° 04'.52N, 116° 07'.03E



TMB-RD-2

06° 04'.72N, 116° 07'.18E



TMB-RD-3

06° 04'.63N, 116° 07'.30E



TMB-RD-4

06° 04'.43N, 116° 07'.16E

2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)

3. Chart affected – MAL 8608

4. Cancel this notice 26 Nov 22.

.....