

156(T)*/2022 MALAYSIA – Sabah – Teluk Sepangar – Buoy.

Source: Royal Malaysian Navy.

1. Buoy *Fl. Y*, in position 06°04'.53N, 116°06'.36E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Chart affected – MAL 8608
-