

160*/2023 MALAYSIA – Terengganu – Pelabuhan Kertih – Light Buoy.

Source: Marine Department of Malaysia No. 223/2023.

1. Paton Bank Kertih Buoy, *Fl.R.5s8M*, in position 04°32'.67N, 103°31'.37E is restored to normal.
 2. Former Notice No. 148(T)*/23 is cancelled.
(WGS84)
 3. Chart affected – MAL 6441.
-