

189(T)*/2022 MALAYSIA – Sarawak – Tg. Similajau – Buoy.

Source: Sarawak Marine Department No. 159(T)/2022.

1. Racon buoy *Fl.5s*, in position 03°38'.04N, 113°15'.37E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 741.
-