

38(T)*/2024 MALAYSIA – Sarawak – Tanjung Baram – Buoy.

Source: Sarawak Marine Department No. 13(T)/2024.

1. Starboard Hand Buoy No. 1, *Fl.G.4s*, in position 04°36'.35N, 113°55'.87E is missing
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Chart affected – MAL 752.
-