

54(T)*/2023 MALAYSIA – Sarawak – Tanjung Baram – Buoy.

Source: Sarawak Marine Department No. 44(T)/2023.

1. Port Hand Buoy No. 2, *Fl.R.4s*, in position 04°37'.27N, 113°56'.18E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 752.
-