

106*/2023 MALAYSIA – Sarawak – Tanjung Baram – Light Buoy.

Source: Sarawak Marine Department No. 91/2023.

1. Starboard Hand Buoy No. 1, *Fl.G.4s*, in position 04°36'.90N, 113°55'.90E is restored to normal and move 04°36'.35N, 113°55'.87E.
 2. Former Notice No. 40(T)*/23 is cancelled.
(WGS84)
 3. Charts affected – MAL 752.
-