

204(T)*/2021 MALAYSIA – Sabah – Sandakan – Beacon.

Source: National Hydrographic Centre.

1. Batuan Sim sim Beacon FL(2)5s, in position 05°50'.13N, 118°07'.34E is temporarily unlit.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 8617
-