

**108(T)\*/2022 MALAYSIA – Johor – Tg. Piai – buoy.**

**Source: Marine Department of Malaysia No. 103/2022(T).**

1. Piai Special Mark, *Fl(1).Y.5s*, in position 01°14'.28N, 103°29'.73E is missing.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Chart affected – MAL 5129
-