

83*/2024 MALAYSIA – Kelantan – Kuala Tok Bali – Light Buoys.

Source: Marine Department of Malaysia No. 77 and 78/2024.

1. Tok Bali Port Limit Light Buoy No. 2, *Fl. Y. 10s*, in position 05°54'.10N, 102°32'.91E and Tok Bali 2G Light Buoy, *Fl(2)G.6s*, in position 05°54'.73N, 102°29'.34E are restored to normal.
 2. Former Notice No. 70(T)*/24 is cancelled.
(WGS84)
 3. Chart affected – MAL 6603.
-