

136(T)*/2022 MALAYSIA – Selangor – Pulau Indah – Buoy.

Source: Marine Department of Malaysia No. 145(R)/2022.

1. Mahang 1 buoy, *Fl.G.2s*, in position 02°54'.36N, 101°16'.47E is unlit.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Chart affected – MAL 5255
-