

247(T)*/2024 MALAYSIA – Selangor – Batuan Penyu – Buoy.

Source: KD PERANTAU.

1. Penyu Light Bouy, *Fl.G.5s*, in position 03°14'.97N, 101°09'.90E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Chart affected – MAL 5321.
-