

**58(T)\*/2022 MALAYSIA – Melaka – Kuala Linggi – Light Buoy.**

**Source: Marine Department of Malaysia No. 45/2022(T).**

1. Kuala Linggi Light Buoy *F(2)10s*, in position 02°19'.42N, 101°57'.63E is temporarily unlit.
  2. Mariners are advised to navigate with caution in the area.  
(WGS 84)
  3. Charts affected – MAL 54
-