107*/2022 MALAYSIA – Melaka – Kuala Linggi – Light Buoy.

Source: Marine Department of Malaysia No. 95/2022.

- 1. Kuala Linggi Light Buoy Fl(2)10s, in position 02°19'.42N, 101°57'.63E is restored to normal.
- 2. Former Notice No. 58(T)*/22 is cancelled. (WGS84)

3. Chart affected – MAL 54	
----------------------------	--