

**247(T)\*/2024 MALAYSIA – Selangor – Batuan Penyu – Buoy.**

**Source: KD PERANTAU.**

1. Penyu Light Bouy, *Fl.G.5s*, in position 03°14'.97N, 101°09'.90E is missing.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Chart affected – MAL 540.
-