

MAL 5419

178/2016(T) MALAYSIA – Perak – Selat Manjung (Dinding) – Light Beacon – Unlit.

Source: Marine Department of Malaysia Notice No. 82/2016(T).

Chart MAL 5419 (Last Correction 141/2016) WGS 84 DATUM

Insert legend, (*Unlit*) for
Dinding Bn, FI(2)G.5s6M 04° 14'.68N, 100° 34'.88E

179/2016(T) MALAYSIA – Perak – Selat Manjung (Dinding) – Light Beacon – Unlit.

Source: Marine Department of Malaysia Notice No. 83/2016(T).

Chart MAL 5419 (Last Correction 178/2016) WGS 84 DATUM

Insert legend, (*Unlit*) for
River Rk, FI.WRG.3s8m7-4M 04° 14'.57N, 100° 35'.32E

163(T)*/2018 MALAYSIA – Perak – Tg. Batu Putih – Light buoy.

Source: Marine Department of Malaysia No. 84(T)/2018.

1. Dinding Light buoy, Q.G, in position 04°15'.00N, 100°35'.42E is off station.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 5419.
-

253*/2018 MALAYSIA – Perak – Pulau Mentago and Selat Dinding – Obstructions.

Source: National Hydrographic Centre.

Chart MAL 5419 (Last Correction 163/2018) WGS 84 DATUM

Insert  *obstrn*

(1)	04° 13'.93N,	100° 32'.09E
(2)	04° 14'.02N,	100° 32'.09E
(3)	04° 13'.95N,	100° 32'.13E
(4)	04° 14'.26N,	100° 32'.03E
(5)	04° 14'.03N,	100° 32'.03E
(6)	04° 14'.12N,	100° 32'.00E
(7)	04° 14'.40N,	100° 31'.94E
(8)	04° 14'.29N,	100° 31'.93E
(9)	04° 14'.17N,	100° 32'.02E
(10)	04° 14'.25N,	100° 31'.99E
(11)	04° 14'.03N,	100° 32'.21E
(12)	04° 14'.16N,	100° 32'.09E
(13)	04° 14'.13N,	100° 32'.12E
(14)	04° 14'.01N,	100° 32'.15E
(15)	04° 14'.15N,	100° 32'.06E
(16)	04° 14'.14N,	100° 32'.07E

(17)	04° 14'.11N,	100° 32'.06E
(18)	04° 14'.03N,	100° 32'.07E
(19)	04° 16'.47N,	100° 34'.27E
(20)	04° 16'.50N,	100° 34'.30E
(21)	04° 16'.53N,	100° 34'.28E
(22)	04° 16'.49N,	100° 34'.36E
(23)	04° 16'.65N,	100° 34'.29E
(24)	04° 16'.77N,	100° 34'.11E
(25)	04° 16'.46N,	100° 34'.21E
(26)	04° 16'.67N,	100° 34'.38E
(27)	04° 16'.71N,	100° 34'.41E
(28)	04° 16'.38N,	100° 34'.32E
(29)	04° 16'.43N,	100° 34'.11E

33*/2019 MALAYSIA – Perak – Sungai Manjung (Dinding) – Blocks.

Source: National Hydrographic Centre.

Chart MAL 5419 (Last Correction 253/2018) WGS 84 DATUM

Insert the accompanying block, centred on: (a) 04° 14'.57N, 100° 35'.34E
(b) 04° 17'.68N, 100° 35'.43E

127(T)*/2019 MALAYSIA – Perak – NE Kg. Teluk Gedung – Buoy.

Source: Royal Malaysian Navy.

1. Selat 2R, *Fl.R.3s*, in position 04°15'.13N, 100°34'.71E is temporarily unlit.
2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
3. Charts affected – MAL 5419.