

154(T)*/2022 MALAYSIA – Pulau Langkawi – P.Enggang – Buoys.

Source: KD PERANTAU.

1. Bouy Enggang 1Y *Fl. Y10s* and Enggang 2Y *Fl(4)Y. 10s*, in position 06°14'.20N, 099°53'.40E and 06°15'.00N, 099°53'.50E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Charts affected – MAL 5630
-