

126(T)*/2021 MALAYSIA – Pahang – Sungai Kuantan – Buoy.

Source: Marine Department of Malaysia No. 65/2021(T).

1. Wreck Buoy *Fl. Y.5s*, in position 03°47'.45N, 103°21'.16E is temporarily unlit.
 3. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 4. Charts affected – MAL 6359
-