

**140(T)\*/2021 MALAYSIA – Pahang – Pelabuhan Kuantan – Light Buoy.**

**Source: Marine Department of Malaysia No. 130/2021(T).**

1. Inner Light Buoy *LFl. 10s*, in position 03°55'.52N, 103°29'.15E is temporarily unlit.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Charts affected – MAL 6359
-