## 57(T)\*/2022 MALAYSIA – Pahang – Tg. Gelang – Light Buoy.

Source: Marine Department of Malaysia No. 29R/2022.

- 1. Outer Light Buoy *Iso.6s6M*, in position 03°55'.73N, 103°33'.05E is destroyed and move to 03°54'.75N, 103°33'.19E.
- 2. Mariners are advised to navigate with caution in the area. (WGS84 DATUM)

2	Charte	affected -	$I \wedge I \wedge I$	6400	
ა.	Charis	anected –	IVIAL	. <b>04</b> UU	