## 221(T)\*/2021 MALAYSIA – Terengganu – Pelabuhan Kemaman – Light Buoy.

Source: Marine Department of Malaysia No. 190/2021(T).

- 1. Outer Light Buoy Fl.R.5s, in position 04°14′.60N, 103°26′.25E is temporarily unlit.
- 2. Mariners are advised to navigate with caution in the area. (WGS 84)
- 3. Charts affected MAL 6416