

68(T)*/2024 MALAYSIA – Sarawak – Tanjung Po – Buoy.

Source: Sarawak Marine Department No. 44(T)/2024.

1. No. 7 buoy, *Fl.G.5s*, in position 01°41'.08N, 110°32'.41E is missing.
 2. Mariners are advised to navigate with caution in the area.
(WGS84 DATUM)
 3. Chart affected – MAL 7150.
-