

**56(T)\*/2023      MALAYSIA – Sarawak – Tanjung Po – Buoy.**

**Source: Sarawak Marine Department No. 40(T)/2023.**

1. Buoy No. 4, *Fl.R.5s*, in position 01°45'.25N, 110°32'.13E is unlit.
  2. Mariners are advised to navigate with caution in the area.  
(WGS84 DATUM)
  3. Charts affected – MAL 7150.
-